

To Ground on machine (terminate at quill shaft nut)

Adjust RV 1 so panel meter has Full Scale Deflection when Gnd & quill led are connected together.